



# **WARMAN METALS** **TUFF RIB**



## SCREW APPLICATION



### CORRECT

Sealing material slightly visible at edge of metal washer. Assembly is weather tight.



### TOO LOOSE

Sealing material not visible. Not enough compression to seal properly.



### TOO TIGHT

Metal washer deformed. Sealing material extruded beyond edge of washer.

ALLOWABLE LOADS (PSF)					
GAUGE		2'-0"	2'-6"	3'-0"	3'-6"
29 Gauge	S	143	92	64	47
	D	79	40	23	15



BOTTOM LAP  
FASTENING PROCEDURE 1) TOP AND BOTTOM ENDS



- 2) INTERMEDIATE - ONE FASTENER BESIDE RIB
- 3) MINIMUM FASTENER LENGTH 1"
- 4) WHEN ORDERING USE 100 SCREWS PER 100 SQUARE FEET